

# Oil Field Environmental Incident Summary

**Incident:** 20141208132111 **Date/Time of Notice:** 12/08/2014 13:21

**Responsible Party:** Unknown (Illegal Dump)

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** MONT 3-3403H

**Field Name:** PAINTED WOODS

**Well File #:** 19409

**Date Incident:** 12/7/2014 **Time Incident:** 13:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 102

**Sec:** 34

**Qtr:**

**Location Description:** 1.25 miles East of 145th Ave NW on 55th St NW.

**Submitted By:** Chance Leininger

**Received By:**

**Contact Person:** N/A N/A

Unknown

Williston, ND 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels			5	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/26/2015

**Clean Up Concluded:** 1/3/2015

**Risk Evaluation:**

No immediate risk

**Areal Extent:**

Down 145th Ave NW & 55th St NW.

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

Affected soil on Mont 3-3403H location will be scraped up and replaced. Remediated on site.

**Wastes Disposal Location:** Remediated on site.

**Agencies Involved:** Dennis Nelson with Williams County hwy Dept

**Updates**

---

**Date:** 12/9/2014    **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

NDDoH inspector was on site at 3:35 p.m. and spoke to EOG representative by phone. EOG video camera caught pale blue truck with red trailer come on to the wellpad with the valve open, dumping apparent brine. Company name was not visible. Driver appeared to be coming from the east. The well pad has been cleaned, and EOG is working with NDIC staff. For about 1/4 mile east of well site on 55th, it appears the road has been scraped/cleaned. No clear markings left on road to indicate location of brine on roadway(s).

---

**Date:** 12/18/2014    **Status:** Reviewed - Follow-up Required

**Author:** Cooper, Mike

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrive on site at approximately 9:00am. Temperature 21F, Wind 0-5mph North. The spill which occurred on the location road had been grated and the material disposed of. However, upon further inspection of the site, it was noticed that a large amount of saltwater had made its way down both sides of the road, impacting areas off of location. Areas off-site were delineated and marked with pink flags, pictures taken. The company rep was contacted and shown the extent of the impact off-site. Conductivity readings were taken on both sides of the road to help delineate impact. Inspector has been in contact with company lead HSE who has been instructed to contact NDIC for further information on the clean-up. Company has been instructed to take samples following excavation to verify clean up. The land owner still needs to be contacted to fill them in on the situation. Further follow-up is required to check for excavation, disposal and vegetative growth in the contaminated area.

---

**Date:** 2/4/2015    **Status:** Correspondence

**Author:** Cooper, Mike

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Talked with Danielle Dupay at 8:50 a.m. The site has been cleaned up, and the soil that was stored in Sawyer, N.D. has been disposed of. It was communicated to Danielle that confirmation samples will need to be taken either by EOG Resources or an NDDoH spill response team member to confirm the excavation site is clean. The excavation site has been left open as no top soil has been added. Followup is required as samples will need to be taken, and soil will need to be replaced and seeded.

---

**Date:** 6/24/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

6/24/2015 at 16:39, on location. Took samples within affected area.

---

**Date:** 4/11/2016    **Status:** Inspection

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Visited the site at 14:56 on 4/8/2016 and found no visible signs of impact. The area is re-vegetating well. No further action is warranted.

---

**Date:** 4/18/2016    **Status:** Correspondence

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Bill Suess sent a No Further Action letter dated April 18, 2016.